





AKERS


High Back Dining Room Chair #1

Walt Akers
ThanksGiving 1999

Directional Views of Assembled Chair




Side




Front

Exploded Views of Chair


- A) Front Leg
- B) Rear Leg
- C) Front Seat Rail
- D) Heel Rail
- E) Rear Seat Rail
- F) Lower Back Receiver
- G) Upper Back Receiver
- H) Rear Base Rail
- I) Back Side Panels
- J) Back Center Panel
- K) Side Seat Rail
- L) Lower Side Rail
- M) Base Side Panel
- N) Base Center Panel



Front




Back




Side


Rear Leg (2 each)




Front Leg (2 each)



Narrow Base Panel (2 each)




Broad Base Panel (4 each)




Broad Back Panel (2 each)

Side View




Front View




Narrow Back Panel (2 each)

Side View




Front View




Front Seat Rail (1 each) /
Rear Seat Rail (1 each)

Front View




Top View




Heel Rail (1 each) /
Rear Base Rail (1 each)

Front View




Top View




Lower Back Receiver Rail

Front View




Top View




Side Seat Rail (2 each)

Front View




Top View




Lower Side Rails (2 each)

Front View




Top View



Upper Back Receiver

Front View



Top View

